

JACKSON HOLE AIRPORT	FIELD
CONDITION & FRICTION MEASUREMENT	
REPORT	

SARSYS SAAB FRICTION TESTER (SFH)

DATE: 4/14/2010

TIME: 6:00

FIELD CONDITIONS

RUNWAY 19		RUNWAY 01	
TOUCHDOWN =	40+	TOUCHDOWN =	40+
MID =	40+	MID =	40+
ROLLOUT =	40+	ROLLOUT =	40+
RUNWAY 01/19 CONDITON N.O.T.A.M.			
TAXIWAY N.O.T.A.M.			
TAXIWAY A MU:	A1 - A2	A2-A3	A3-A4
	40+	40+	40+
RAMP N.O.T.A.M.			
RAMP MU:	COMMERCIAL		GENERAL AVIATION
	40+		40+
COMMENTS			
REPORTED TO:		LOCKHEED MARTIN, PRESCOTT HUB 1-877-4-US-NTMS	
FSS	<input checked="" type="checkbox"/>	INITIAL <u>Prior LJ</u>	TOWER <input checked="" type="checkbox"/>
JHAB	<input checked="" type="checkbox"/>	JHAV	<input checked="" type="checkbox"/>
WWFS	<input type="checkbox"/>	SWA <input checked="" type="checkbox"/>	UNITED <input checked="" type="checkbox"/>
NWA	<input type="checkbox"/>	LYNX	<input type="checkbox"/>

REPORTING OFFICER: P. Walters

TIME: 6:00